

FORM



6

Rev
11/20

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:
403547358

Date Received:

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number:10633

Contact Name:Adam Conry

Name of Operator:CRESTONE PEAK RESOURCES OPERATING LLC

Phone:(303) 883-3351

Address:1801 CALIFORNIA STREET #2500

Fax:

City:DENVERState:COZip:80202

Email:AConry@civiresources.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:

☐ Notice of Intent to Abandon

☒ Subsequent Report of Abandonment

API Number05-005-06390-00

Well Name:GRIMM-TINIANOWWell Number:1

Location:QtrQtr:SWSWSection:34Township:4SRange:64WMeridian:6

County:ARAPAHOEFederal, Indian or State Lease Number:

Field Name:WILDCATField Number:99999

Only Complete the Following Background Information for Intent to Abandon

Latitude:39.653795Longitude:-104.544668

GPS Data:GPS Quality Value:Type of GPS Quality Value:PDOPDate of Measurement:08/25/1979

Reason for Abandonment:

☐ Dry

☐ Production Sub-economic

☐ Mechanical Problems

☐ Other

Casing to be pulled:

☐ Yes

☐ No

Estimated Depth:

Fish in Hole:

☐ Yes

☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes

☐ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	206	150	206	0	CALC
OPEN HOLE	7+7/8				206	8330				

Date Run: 10/11/2023 Doc [#403547358] Well Name: GRIMM-TINIANOW 1

Page 1 of 3

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	70	sks cmt from	7566	ft. to	7366	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	50	sks cmt from	3200	ft. to	3100	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	150	sks cmt from	2000	ft. to	1675	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	1250	sks cmt from	1400	ft. to	206	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	25	sks cmt from	206	ft. to	0	ft.	Plug Type:	CASING	Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 09/10/2023 Cut and Cap Date: 09/27/2023 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 17

*Wireline Contractor: _____

*Cementing Contractor: AXIS

Type of Cement and Additives Used: CLASS G, THIXO

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

- Venting health and safety precautions were taken to avoid nuisance and or hazards to the public.
 - Operator reviewed the stormwater program and implemented stormwater BMPs and erosion control measures as needed to prevent fine-grained sediment and impacted stormwater runoff from entering surface water.
 - Form 42 was submitted prior to plugging operations, Form 42 Doc # 403516338. Form 42 was submitted prior to MIRU for plugging operations, Form 42 Doc # 403516327.
 - No fluids or gas migration was present prior to cement plug to surface being set. The plug was cemented to surface with 25 sacks of cement from 206' - 0'.
 - At least 100' of cement was left in the wellbore for each plug.
 - This form 6-SRA addresses all COA's from the Form 6-NOIA.
 - As-Drilled GPS Data is attached to this form.
- Attached to this form:
1. Cement tickets are attached to this form.
 2. Operations summary is attached to this form for reference.
 3. Final P&A WBD is attached to this form.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Ashley Noonan

Title: Sr. Regulatory Analyst

Date: _____

Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:**COA Type****Description**

0 COA	

Attachment List**Att Doc Num****Name**

403549733	CEMENT JOB SUMMARY
403549741	WELLBORE DIAGRAM
403549742	OPERATIONS SUMMARY

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)