

GOLDEN EAGLE 18-15 API# 05-071-08799 – OGRIS OPERATING
COGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 11, 2023
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #713600233



PHOTO 1: THE NOXIOUS WEEDS ON THE FILL SLOPE WERE TREATED ON 9/26/23. THE LOCATION WILL BE RE-TREATED AS NEEDED.

GOLDEN EAGLE 18-15 API# 05-071-08799 – OGRIS OPERATING
COGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 11, 2023
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #713600233



PHOTO 2: A DIVERSION DITCH WAS CREATED ALONG THE TOP OF THE FILL SLOPE TO DIRECT STORM WATER OFF LOCATION AND PREVENT RILLING ON THE SLOPE. ROCK CHECK DAMS WERE INSTALLED TO CONTROL RUN ON VELOCITY.

GOLDEN EAGLE 18-15 API# 05-071-08799 – OGRIS OPERATING
COGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 11, 2023
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #713600233



PHOTO 3: STRAW BLANKETS WERE INSTALLED OVER THE ENTIRE FILL SLOPE. ALL DISTIRBED AREAS WERE TRACKED, SEEDED, AND HYDROMULCHED TO FURTHER PROMOTE STABILIZATION THROUGH VEGETATIVE GROWTH.