

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2023

Submitted Date:

10/05/2023

Document Number:

699107520

**FIELD INSPECTION FORM**

Loc ID 329904 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
329904	LOCATION	AC			-	HSR ANNE STATE-63N61W 7NESE	SI

**General Comment:**

[Inspection on the tank battery](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment on location needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2023
Type	WEEDS		
Comment:	Overgrown vegetation throughout the location need to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	50 BBLs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.238300,-104.246700
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 329904 Type: LOCATION API Number: - Status: AC Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI Tank Battery

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      On Tuesday 10/3/23 at approximately 1054hrs I, Inspector Adam Burns, Conducted an on-site inspection at HSR Anne State-63N61W 7NESE Tank Battery of KP Kauffman Company INC.                      Location Id: 329904 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Overgrown vegetation throughout the location need to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/20/23                      Unused Equipment on location needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/20/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	10/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403551945	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275516">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275516</a>
699107521	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275486">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275486</a>