

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2022

Submitted Date:

11/09/2022

Document Number:

690203565

FIELD INSPECTION FORM

Loc ID 309227 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE


Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290428	WELL	PR	07/13/2007	CBM	071-09267	BLACK GOLD 32-33	RI
301143	PIT	AC	01/07/2010		-	BLACK GOLD 32-33	AC

General Comment:

 EVERGREEN NATURAL RESOURCES	COGCC Work Order	Stormwater: Roustabout
COGCC Submitted Date: 11/8/2022	Document # 690203565	COGCC Deadline Date: 11/11/2022
Contractor Assigned:	Well Name: Black Gold 32-33	
Contractor Completion Signature:	Contractor Completion Date:	
Foreman Completion Signature:	Foreman Completion Date:	
Contractor and Foreman must sign upon completion. Please email Susan at susan.wolfram@enrllc.com and attach <u>Field Ticket and Photos</u>		

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
	Flow Line	<= 1 bbl		
Comment:	There is stained soils at the meter shed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 11/16/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues were observed during inspection.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced Water Lined: YES Pit ID: 301143 Lat: 37.301950 Long: -104.784600

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:Liner Type: Plastic Liner Condition: InadequateComment: There are holes in the pit liner.Corrective Action: Pit liner compromised (Rule 910). Reduce fluid level in pit.Date: 11/11/2022**Fencing:**

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action: _____

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	301143	1941979	
	301143	1941979	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203566	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5911035