

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2023

Submitted Date:

10/12/2023

Document Number:

699107568

FIELD INSPECTION FORM

Loc ID 305609 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279948	WELL	SI	07/01/2020	GW	123-23239	LOST CREEK 27	TA

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Access road will need to be maintained in the near future with overgrown vegetation		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 50%;" type="text"/>
Corrective Action:	<input style="width: 50%;" type="text"/>
	Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation around the well needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	10/25/2023
Type	TRASH		
Comment:	Trash near the well needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606	Date:	10/25/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 279948 Type: WELL API Number: 123-23239 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/01/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403257185 indicates it was last tested on 12/16/20. 11/14/2023

Corrective Action: Submit reports as per Rule 419. Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 10/9/23 at approximately 1012hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lost Creek 27 of O'Brien Energy Resources Corp. API #05-123-23239 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Overgrown vegetation around the well needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/25/23 Trash near the well needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/25/23 No updated annual BH test on file. Submit reports. Form 17 #403257185 indicates it was last tested on 12/16/20. Submit reports as per Rule 419. With a Corrective Action date of 11/14/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	10/12/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403558878	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6282542
699107569	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6282518