

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403524162

Date Received:

09/08/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Distribution, Evergreen

719-846-7898

cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695108567

Inspection Date: 08/16/2023

FIR Submit Date: 08/16/2023

FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307664

Location Name: MAFIA-633S65W Number: 32SWSW County: LAS ANIMAS

Qtrqr: SWS Sec: 32 Twp: 33S Range: 65W Meridian: 6
W

Latitude: 37.121760 Longitude: -104.700660

FACILITY - API Number: 05-071- -00 Facility ID: 89188

Facility Name: MAFIA Number: 1432

Qtrqr: SWS Sec: 32 Twp: 33S Range: 65W Meridian: 6
W

Latitude: 37.121760 Longitude: -104.700660

CORRECTIVE ACTIONS:

1 ☒ CA# 179084

Corrective Action: REMOVE OR MARK UNUSED RISERS PER RULE 606.

Date: 09/16/2023

Response: CA COMPLETED

Date of Completion: 09/01/2023

Operator Comment: Risers labeled per rule 606

COGCC Decision: Approved via an AMI

Date: 09/16/2023

Date of Completion: 09/07/2023

Stormwater repairs made per rule 1002

Approved via an AMI

Comment:	Please use this FIRR to address inspection #695108567 and failed FIRR #403504860
----------	--

Signed:

Date: 9/8/2023 9:34:12 AM

<u>Document Number</u>	<u>Description</u>
403524162	FIR RESOLUTION SUBMITTED
403524167	Marked risers
403524168	Stormwater repairs

Page 2 of 2