



Chevron U.S.A. Inc.

100 Chevron Road Phone (303) 675-3700
Rangely, CO 81648

00065407

RECEIVED

SEP 24 1986

OIL & GAS COM. COMM

R. H. Elliott
Unit Superintendent

September 19, 1986

**POLFAM EXPLORATION COMPANY
GOVERNMENT 2-10
SEC 3, T1N, R102W
RANGELY FIELD
RIO BLANCO COUNTY, COLORADO**

*1380 Lawrence St. Ste 1450
Denver 80204
534-0714*

State of Colorado
Oil & Gas Conservation Commission
Department of Natural Resources
Suite 380, Logan Tower Building
1580 Logan Street
Denver, Colorado 80203

Attention: Mr. Frank J. Piro
Deputy Director - Secretary

Gentlemen:

Chevron U.S.A. objects to the completion of the above subject well due to the bottomhole location. Based on the attached "Application for Permit to Drill, Deepen, or Re-enter and Operate" and directional survey, the calculated bottomhole location is approximately 567 feet from the Rangely Weber Sand Unit boundary. The bottomhole location is in violation of Cause Order 2-32, Rule 5 (c) and the attached agreement between Polfam Exploration Company and Chevron U.S.A. Inc.

Very truly yours,

CHEVRON U.S.A. INC.

R. H. Elliott

R. H. Elliott, Unit Superintendent

*only withdrawn 12/3/86
unf*

LSM:nbw

Attach.

cc: Mr. P. L. Meek
Oil & Gas Commission File

*Phone Call 9/25/86
- Requested this site
application for hearing
7/20*

*Phone call Tip Columbus
(Polfam)
10/21/86 -*