

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403581020

Date Received:  
11/02/2023

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10670  
Name of Operator: BISON IV OPERATING LLC  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>GARZA, TARAH</u>		<u>tgarza@bisonog.com</u>
<u>GILLEN, KATIE</u>		<u>kgillen@bisonog.com</u>
<u>AKERS, JOHN AUSTIN</u>		<u>aakers@bisonog.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708200620  
Inspection Date: 10/13/2023 FIR Submit Date: 10/18/2023 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BISON IV OPERATING LLC Company Number: 10670  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 458635

Location Name: Blue Teal Number: 22-C Pad County: \_\_\_\_\_  
Qtrqtr: NWNE Sec: 22 Twp: 8N Range: 60W Meridian: 6  
Latitude: 40.653502 Longitude: -104.075711

### FACILITY - API Number: 05-123-00 Facility ID: 458635

Facility Name: Blue Teal Number: 22-C Pad  
Qtrqtr: NWNE Sec: 22 Twp: 8N Range: 60W Meridian: 6  
Latitude: 40.653502 Longitude: -104.075711

### CORRECTIVE ACTIONS:

**1** CA# 185415

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.

Date: 10/13/2023

Response: CA COMPLETED

Date of Completion: 10/19/2023

Operator Comment: In accordance with Rule 606, trash and rubbish have been removed from the site and disposed of properly. See the attached photographs.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 185416

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.

Date: 10/13/2023

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 10/19/2023

Operator  
Comment:

In accordance with Rule 606, unused equipment has been removed from the site. See the attached photographs.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 185417

Corrective Action: Comply with Rule 1003. The location will remain out of compliance until the corrective actions have been resolved.

Date: 10/13/2023

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 10/19/2023

Operator  
Comment:

Corrective actions were taken to remove weeds in accordance with Rule 1003. See the attached photographs.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bryce Maifeld

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 11/2/2023 9:02:55 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403581488	Photographs
-----------	-------------

Total Attach: 1 Files