

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/15/2023

Document Number:

699107864**FIELD INSPECTION FORM**Loc ID 332875 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	
,		cogcc@kpk.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247879	WELL	PR	03/01/2019	GW	123-15677	OCOMA 31-25	PR

**General Comment:**

on-site inspection to prior inspection document # 699106698, prior inspection document #699106845, prior inspection document #699106964, FIRR #403463261, prior inspection document #699107095, & FIRR #403474035. CA has not been corrected.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused panel fence needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 11/27/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	Appears to be leaking around the threads of the wellhead and needs repaired. See attached photo		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 05/29/2023
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 247879 Type: WELL API Number: 123-15677 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/16/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday 11/15/23 at approximately 0822hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document # 699106698, prior inspection document #699106845, prior inspection document #699106964, FIRR #403463261, prior inspection document #699107095, &amp; FIRR #403474035, at Ocoma 31-25 of KP Kauffman Company INC, at API# 05-123-15677 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Appears to be leaking around the threads of the wellhead and needs repaired. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a Corrective Action date of 5/29/23</p> <p>New CA below:</p> <p>Unused panel fence needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 11/27/22</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>Issue not remediated since initial inspection corrective action dates in May 2023.</p> <p>This is a summary of inspection report.</p>	burnsa	11/15/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107865	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6323175">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6323175</a>