

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/09/2023

Document Number:

702502111

**FIELD INSPECTION FORM**Loc ID 313060 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10776

Name of Operator: CROWHEART ENERGY LLC

Address: 1225 17TH STREET SUITE 2950

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Regulatory		regulatory@crowheartenergy.com	
Fiddles, Callie	(720) 738-9443	c.fiddles@crowheartenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223491	WELL	TA	09/01/2020	GW	081-06857	PEPLER FEE COM 12-18	TA

**General Comment:****ECMC Inspection Report Summary**

On Tuesday, 11/07/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Crowheart Energy LLC on the Pepler Fee Com 12-18 well, Location #313060, in Moffat County, Colorado.

This location is within or in close proximity to a CPW District with High Priority, NSO, and Density Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501380 on 5/24/23 and Inspection #702501872 on 9/19/23. The following Corrective Actions have not been resolved and original due dates will remain:

1. Debris.
  2. Wellhead sign missing required information.
- Refer to Inspection Photos for observed compliance issues.

While on location no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Wellhead sign illegible and missing required information.		
Corrective Action:	Operators will ensure that signs are well maintained and legible. When no associated Tank battery is present at the Oil and Gas Location, the following information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Well; Well name(s) and API number(s); The legal location of the Well(s) including the quarter/quarter section.	Date:	10/20/2023

Emergency Contact Number:

Comment: 800-967-2801

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	06/01/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Wellhead tree		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	223491	Type:	WELL	API Number:	081-06857	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: MIT - 7/21/2020									
Corrective Action:									
Date:									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:  Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403591651	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317707">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317707</a>
702502117	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317688">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317688</a>