

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403582215

Date Received:

11/02/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

javier.pellacani@chevron.com

rbucogccinspectionreports@chevron.onmicrosoft.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708200622

Inspection Date: 10/13/2023

FIR Submit Date: 10/18/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 431544

Location Name: Hunt Number: LF18-62HN County: \_\_\_\_\_  
Multi

Qtrqr: NENE Sec: 19 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.653797 Longitude: -104.126003

### FACILITY - API Number: 05-123- -00 Facility ID: 431544

Facility Name: Hunt Number: LF18-62HN  
Multi

Qtrqr: NENE Sec: 19 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.653797 Longitude: -104.126003

### CORRECTIVE ACTIONS:

1 ☒ CA# 185418

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been addressed.

Date: 10/13/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator Comment: Complied with rule 606. Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 ☒ CA# 185419

Corrective Action: Operator shall immediately ensure operations are safe and will properly install safety controls for the observed hole/subsidence pursuant to Rule 602.c. Corrective action date is the date the location was observed out of compliance.

Date: 10/13/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator Comment: Complied with rule 602.c. Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 ☒ CA# 185420

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.

Date: 10/13/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator Comment: Complied with rule 606. Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Complied with rule 602.c. and 606. Please see attached pics

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Isaiah Flores

Signed: \_\_\_\_\_

Title: HSE

Date: 11/2/2023 1:42:50 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403582215	FIR RESOLUTION SUBMITTED
403582225	pic
403582227	pic

Total Attach: 3 Files