

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2023

Submitted Date:

11/15/2023

Document Number:

689501462**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeterson@kpk.com	KPK environmental
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479923	SPILL OR RELEASE	CL			-	George Norden Consolidation	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 479923/Remediation Project No 19716. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

Comment: Weeds growing on location and around the open excavation.

Corrective Action: Comply with Rule 606.

Date: 11/27/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type

Comment: Fencing beginning to fall in some areas of the excavation and weeds have grown through the fencing.

Corrective Action: Operators will fence or cover open trench/excavation to prevent access when sites are not attended Remediation Safety fence Rule 913.b.(5)B.

Date: 11/15/2023

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation excavation is open. Water was observed within the excavation. No sheen was observed on the water. Salt crusting was observed on excavation side walls.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: Quarterly reporting is required for Remediation Project #19716. Operator is past due on quarterly reporting. The last approved Supplemental Form 27 was received on August 24, 2022 (Doc # 403143480).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule. Operator will maintain quarterly reporting until the site investigation is complete and the implementation schedule can be updated. This location was included in NOAV # 403513701 for violation of Rule 913.e.(3)

Date: 11/22/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403597318	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324793
689501463	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324726