

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/07/2023

Document Number:

713600466**FIELD INSPECTION FORM**Loc ID 309138 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ogris		gward@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288589	WELL	PR	10/31/2007	CBM	071-09135	NEW ELK 36-3	RI

General Comment:

This is a Location and Stormwater Management Inspection for Location #309138.
See attached photos and additional details within this report.

Location

Lease Road:			
Type	Access		
comment:	Road is graded and maintained.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	The fencing at the lined pit is not maintained or adequate to prevent livestock or wildlife entry. No extended CA date is applied and the corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a and wildlife protection rules	Date:	12/05/2023

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is stained soils next to the engine skid. No extended CA date is applied and the corrective action will remain out of compliance until completed.

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Immediate clean up of spilled material.

Date: 12/05/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	292669	2059181	
	292669	2059181	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600467	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349241