

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2023

Submitted Date:

12/21/2023

Document Number:

702502231

FIELD INSPECTION FORMLoc ID 312935 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Evans, Clay	(307) 380-7616	clay@antler-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222917	WELL	PR	05/01/2023	GW	081-06278	MARTIN-GOVERNMENT 1 (14-8)	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 12/19/2023, Inspector Kirby Burchett, conducted a follow up inspection at Antler Energy LLC on the Martin-Government 1 (14-8) well, Location #312935, in Moffat County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501417 on 6/6/23. Random debris, chemical tanks, drums and containments have been removed. The following corrective actions have not been resolved and the original due dates will remain:

1. Unused equipment.
2. No tank battery sign.
3. Stained soils.
4. Wellhead sign missing required information.
5. Heater stack open to wildlife.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign missing required information		
Corrective Action:	The Wellhead sign will identify: The Well name; The API number; and Its legal location, including the quarter/quarter section.	Date:	08/06/2023
Type	BATTERY		
Comment:	No sign at tank battery.		
Corrective Action:	The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.	Date:	07/07/2023
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616 or 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Out of Service equipment on location		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	06/22/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Tank	<= 1 bbl		
Comment:	Stained soil in and around tank battery			
Corrective Action:	Remove and properly dispose of oily waste and stained soils	Date:	06/22/2023	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Compressor	# 1		corrective date
Comment:	Out of Service. Unused equipment needs to be removed from location.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Partial unit. Unused equipment needs to be removed from location		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	1 unit in service? Unused equipment needs to be removed from location.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator stacks and stack on Production tank missing bird protection.		
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.		Date: 06/17/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities				
Facility ID: 222917	Type: WELL	API Number: 081-06278	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Production Reports - June 2023			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502232	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6368558