

OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO.	
2. NAME OF OPERATOR Snowden Oil Co.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 565 Fort Morgan Colorado 80701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface SE $\frac{1}{4}$ NE - 12 - 2N - 55W 2015 ft from N line 825 ft. from E line. At proposed prod. zone D sand - 4943-47		8. FARM OR LEASE NAME Davie 41636	
14. PERMIT NO. 05 087 7575		9. WELL NO. # 4	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 4527- KB 4537		10. FIELD AND POOL, OR WELDCAT Jubilee	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 12 - 2 N - 55- 6th	
		12. COUNTY Morgan	13. STATE Colorado

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work 9-29-87

M. I. R. U. Pulling unit Lay down rods & tubing Place sand & gravel from 4986 to 4900' Pump down five sacks of cement load casing to surface with water pressure to 2000 PSI hold for thirty minutes plug held O.K. Run in casing cutter & shot off at 4362' Pull & lay down 120 jts. of 5 1/2" casing Fill hole with heavy mud from 4900' to 140' Place fifteen sacks of cement at bottom of surface casing. And a five sack cement plug at top of surface. Level location. Complete work on the 9-30-87

EXHAUSTED
OIL WELL



00075548

RECEIVED
 OCT 19 1987
 COLO. OIL & GAS CONS. COMM.

FOR OFFICE USE ONLY
F1
F2
F3
F4
F5
F6
F7
F8
F9

18. I hereby certify that the foregoing is true and correct

SIGNED

M. A. Snowden

TITLE owner of Snowden Oil Co.DATE 10-8-87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

SUPR. PETROLEUM ENGINEER
Oil & Gas Cons. Comm.

DATE

OCT 23 1987