

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403639021

Date Received:  
12/28/2023

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Luke Kelly

Phone

970-939-6353

Email

lkelly@civiresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696305541

Inspection Date: 12/19/2023

FIR Submit Date: 12/19/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 428713

Location Name: Antelope Number: D-18 County: \_\_\_\_\_

Qtrqr: SESW Sec: 18 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.393721 Longitude: -104.370282

#### FACILITY - API Number: 05-123-00 Facility ID: 428713

Facility Name: Antelope Number: D-18

Qtrqr: SESW Sec: 18 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.393721 Longitude: -104.370282

### CORRECTIVE ACTIONS:

1 CA# 189322

Corrective Action: Comply with Rule 606

Date: 01/19/2024

Response: CA COMPLETED

Date of Completion: 12/27/2023

Operator  
Comment:

Identified tumbleweed debris will consistently be cleared to help maintain the location and comply with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 189323

Corrective Action: Comply with Rule 606

Date: 01/19/2024

Response: CA COMPLETED

Date of Completion: 12/27/2023

Operator  
Comment:

Operator has appropriately removed identified, unused equipment from the location to comply with Rule 606.

COGCC Decision:

COGCC  
Representative:

3 CA# 189324

Corrective Action: Install sign to comply with Rule 605.h.

Date: 01/19/2024

Response: CA COMPLETED

Date of Completion: 12/27/2023

Operator  
Comment:

Operator has appropriately added/updated labels on NE Crude Oil Tank to comply with Rule 605.h.

COGCC Decision:

COGCC  
Representative:

5 CA# 189326

Corrective Action: All Open-ended openings shall be covered at Pipe, Valves and where Heater Stacks were removed.  
Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

Date: 12/22/2023

Response: CA COMPLETED

Date of Completion: 12/27/2023

Operator  
Comment:

Operator has appropriately addressed the (3) Separators that are open and effectively installed coverage to prevent unauthorized discharge to comply with Rule 902.b.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 12/28/2023 3:05:57 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403639248	Inspection Resolution Report

Total Attach: 1 Files