

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403645297

Date Received:

01/04/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

*

rbucogccinspectionreports@chevron.onmicrosoft.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200774

Inspection Date: 12/20/2023

FIR Submit Date: 12/26/2023

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 421062

Location Name: State Number: 8-60 16-1H County: _____

Qtrqr: NW Sec: 16 Twp: 8N Range: 60W Meridian: 6
NE

Latitude: 40.667913 Longitude: -104.093668

FACILITY - API Number: 05-123- -00 Facility ID: 421062

Facility Name: State Number: 8-60 16-1H

Qtrqr: NW Sec: 16 Twp: 8N Range: 60W Meridian: 6
NE

Latitude: 40.667913 Longitude: -104.093668

CORRECTIVE ACTIONS:

1 ☒ CA# 189535

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/20/2023

Response: CA COMPLETED

Date of Completion: 01/04/2024

Operator
Comment: Complied with Rule 606

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 ☒ CA# 189536

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/20/2023

Response: CA COMPLETED

Date of Completion: 01/04/2024

Operator Comment: Complied with Rule 902.b.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Complied with Rule 606 and 902.b.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Javier Pellacani

Signed: _____

Title: HSE

Date: 1/4/2024 4:14:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403645297	FIR RESOLUTION SUBMITTED
403645312	Location Photo
403645314	Location Photo
403645317	Location Photo

Total Attach: 4 Files