

**COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**



00264203

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <u>075 - 09302</u>		LEASE NAME: <u>Ballish 13-31</u>	
LOCATION: <u>NW 34 31-9N-52W</u>		OPERATOR: <u>E.M. Davis</u>	
DATE: <u>4-26-96</u>		INSPECTOR: EBB \ Ed Binkley (970) 842-4465	
Insp. Type: <u>SR</u>	Insp. Status: <u>DA</u>	PA: <input checked="" type="radio"/> Y <input type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> P <input type="radio"/> F Viol.: Y <input checked="" type="radio"/> N NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM (RULE)	COMMENTS	INPUT
Well ID Signs (210)		
Pits (Reserve/Production)(904)		
Fences (604 C.(3), 1003 A.)		
Tank Battery Equipment(604)		
Fire Walls/Berms/Dikes(604)		
General Housekeeping (603g)		
Spills(Oil/Water)(907)	C	
Bradenhead (207)		
Drilling /Workover (315)		
Surface Rehabilitation (317)	<u>Bob Ballish - landowner gave release for mud on location. EB</u>	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission. Submit a copy or FAX to the inspector with date remedied and your signature. EBB fax is 970-842-4467.

White - File Green - Operator Canary - Well Site

9661 - E M M