

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2024

Submitted Date:

01/24/2024

Document Number:

714300021

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Peterson, John		jpeterson@kpk.com	KPK environmental
Graber, Nikki		nikki.graber@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485393	SPILL OR RELEASE	AC	11/08/2023		-	Owen 12-1 Flowline	EI

General Comment:

[This is an environmental inspection to determine progress on Spill ID 485393. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

[There were no operator or contract environmental personnel on location at the time of this field inspection.](#)

[Photos attached to document site conditions.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Fencing around the excavation is inadequate. Fencing has fallen in some areas of the excavation.		
Corrective Action:	Operators will fence or cover open trench/excavation to prevent access when sites are not attended Remediation Safety fence Rule 913.b.(5)B.		Date: 01/31/2024

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 485393 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: A small excavation remains open at the location. No additional excavation appears to have been performed since 10/31/2023 inspection (doc no 689501435).

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Spill ID 485393 remains open.

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i±iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19± Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director. Date: 01/24/2024

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300022	Inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405805