

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403602049

Date Received:
11/21/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 7800
Name of Operator: BEREN CORPORATION
Address: 2020 N BRAMBLEWOOD STREET
City: WICHITA State: KS Zip: 67206

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Krystal Heibel</u>	<u>303-817-5217</u>	<u>krystal.heibel@state.co.us</u>
<u>Kay, Michael</u>	<u>316-249-7597</u>	<u>kaym@berexco.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 709100115
Inspection Date: 09/24/2023 FIR Submit Date: 10/03/2023 FIR Status: _____

Inspected Operator Information:

Company Name: BEREN CORPORATION Company Number: 7800
Address: 2020 N BRAMBLEWOOD STREET
City: WICHITA State: KS Zip: 67206

LOCATION - Location ID: 450327

Location Name: Brewer A Tank Battery Number: _____ County: _____
Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6
Latitude: 40.654909 Longitude: -103.279013

FACILITY - API Number: 05-075-00 Facility ID: 450327

Facility Name: Brewer A Tank Battery Number: _____
Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6
Latitude: 40.654909 Longitude: -103.279013

CORRECTIVE ACTIONS:

1 CA# 182905

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1). Date: 10/24/2023

Response: CA COMPLETED Date of Completion: 10/06/2023

Operator Comment: Pumper filled in and repaired all holes in berms. See attached Figures 1-7.

COGCC Decision: Approved

COGCC Representative: _____

2 CA# 182906

Corrective Action: Inspect, maintain and repair tanks to comply with rule 609.b. Date: 11/03/2023

Response: CA COMPLETED Date of Completion: 10/06/2023

Operator Comment: Burrows underneath tanks filled in and repaired. See attached Figure 2.

COGCC Decision: Approved

COGCC Representative: _____

4 CA# 182908

Corrective Action: Comply with Rule 606 Date: 10/11/2023

Response: CA COMPLETED Date of Completion: 10/06/2023

Operator Comment: Picked up water bottle on location. See attached Figure 1.

COGCC Decision: Approved

COGCC Representative: _____

5 CA# 182909

Corrective Action: Comply with Rule 606 Date: 10/11/2023

Response: CA COMPLETED Date of Completion: 10/06/2023

Operator Comment: Spare chemical drum rack removed from location by foreman.

COGCC Decision: Approved

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator has completed 4 of the 5 corrective actions. We have ordered what we need to bring the tank signs into compliance. Another FIRR will be submitted once the sign work is done.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Kay Signed: _____

Title: Division Engineer Date: 11/21/2023 10:40:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403602049	FIR RESOLUTION SUBMITTED

403602822	Water bottle picked up from location.
403602823	Burrows underneath tanks filled in and repaired.
403602824	Burrows filled in and repaired.
403602825	Burrows filled in and repaired.
403602827	Burrows filled in and repaired.
403602830	Burrows filled in and repaired.
403602831	Burrows filled in and repaired.

Total Attach: 8 Files