

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403601554

Date Received:
12/04/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

7 of 7 CAs from the FIR responded to on this Form

7 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 55030
Name of Operator: MCCARTNEY ENGINEERING LLC
Address: 4251 KIPLING ST STE 575
City: WHEAT RIDGE State: CO Zip: 80033

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>McCartney, Jack</u>	<u>303-830-7208</u>	<u>jack@mccartneyengineering.com</u>
<u>McCartney, Ron</u>		<u>ron@mccartneyengineering.com</u>
<u>Kyle Waggoner</u>		<u>kyle.waggoner@state.co.us</u>
<u>Krystal Heibel</u>		<u>krystal.heibel@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 709100135
Inspection Date: 10/18/2023 FIR Submit Date: 10/27/2023 FIR Status: _____

Inspected Operator Information:

Company Name: MCCARTNEY ENGINEERING LLC Company Number: 55030
Address: 4251 KIPLING ST STE 575
City: WHEAT RIDGE State: CO Zip: 80033

LOCATION - Location ID: 312242

Location Name: RICE-612N54W Number: 33SWNW County: _____
Qtrqr: SWN Sec: 33 Twp: 12N Range: 54W Meridian: 6
W
Latitude: 40.972940 Longitude: -103.418440

FACILITY - API Number: 05-075- -00 Facility ID: 312242

Facility Name: RICE-612N54W Number: 33SWNW
Qtrqr: SWN Sec: 33 Twp: 12N Range: 54W Meridian: 6
W
Latitude: 40.972940 Longitude: -103.418440

CORRECTIVE ACTIONS:

1 CA# 187241

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o. Location will remain out of compliance until the corrective action has been resolved.

Date: 11/28/2023

Response: CA COMPLETED

Date of Completion: 11/28/2023

Operator Comment: Berm in question contains 2- 300 bbl water tanks. Berm measurements by McCartney suggest that berm meets current regulations, however, this existing berm was built up in lower areas to comply with the ECMC inspector's request for corrective action.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 187242

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 11/28/2023

Response: CA COMPLETED

Date of Completion: 11/28/2023

Operator Comment: Minor old oil remnants picked up.

COGCC Decision: Approved

COGCC Representative:

3 CA# 187243

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 11/28/2023

Response: CA COMPLETED

Date of Completion: 11/19/2023

Operator Comment: Evidently inspectors noting old oil stain on side of production tank commenting "Hydrocarbons leaking from top of tank". However, there were no hydrocarbons (oil) leaking from either production tank nor was there any evidence that any such leak occurred. Evidently a pumper had dripped a little oil off his gauge tape while gauging the tank. Cleaned old oil stain from side of tank.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4 CA# 187244

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge.

Date: 11/06/2023

Response: CA COMPLETED

Date of Completion: 11/07/2023

Operator Comment: Wildlife protection was placed over the container holding a 55-gal. empty chemical drum. Regulations exempt "containers" such as this from netting provisions. There were no "unauthorized discharge of E&P waste at this battery site other than evidence of a valve with a very small oil leak which was fixed by tightening the valve packing and the old oil stain on the surface cleaned up.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

5 CA# 187245

Corrective Action: Comply with Rule 606

Date: 11/13/2023

Response: CA COMPLETED

Date of Completion: 11/19/2023

Operator Comment: Glove, section of railroad ties and several pieces of wood, 1" pipe and some small particles of insulation picked up.

COGCC Decision: Approved

COGCC Representative:

COGCC
Representative:

6 CA# 187246

Corrective Action: Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.a.

Date: 11/13/2023

Response: CA COMPLETED

Date of Completion: 12/04/2023

Operator Comment: Note: There is no correct response for this CA, so identified as "CORRECTIVE ACTION COMPLETED" even though no action was taken. Pit in question belongs to the state of Colorado and is not the responsibility of McCartney Engineering, LLC.

COGCC Decision: Approved

COGCC
Representative:

7 CA# 187247

Corrective Action: Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.a.

Date: 11/13/2023

Response: CA COMPLETED

Date of Completion: 12/04/2023

Operator Comment: Note: There is no correct response for this CA, so identified as "CORRECTIVE ACTION COMPLETED" even though no action was taken. Pit in question belongs to the state of Colorado and is not the responsibility of McCartney Engineering, LLC.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This Field Inspection report was greatly exaggerated as there was minimal hydrocarbons on the battery site and there were no Unauthorized Discharges from any pipes at this site. In addition, the inspectors commented under "General Comments" that there were 2 active remediation projects on this site. One was taken care of by a previous operator years ago and the other refers to a pit owned by the state of Colorado. It is my contention that these general comments were not the responsibility of McCartney and should have not been listed on this form.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jack McCartney

Signed: _____

Title: Manager

Date: 12/4/2023 3:13:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403601554	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files