

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2024

Submitted Date:

02/22/2024

Document Number:

699505513

FIELD INSPECTION FORM

Loc ID 318615 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Silver, Randy		randy.silver@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241728	WELL	PR	08/01/2023	GW	123-09517	KLEIN (LANYARD EXTENSION) 24-8	PR

General Comment:

This inspection is for a flowline release that was reported by land owner.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	OTHER			
Comment:		Flowline failure and gas release.		
Corrective Action:		Comply with rule 912.a.		Date: 02/23/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 241728 Type: WELL API Number: 123-09517 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/24/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On 2/22/24 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Klein (Lanyard Extension) 24-8</p> <p>Company Name- KPK</p> <p>Location ID-318615, Flowline ECMC Document # 402029656. Release point is approx. 50' east of tank battery.</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well</p> <p>This is a follow up inspection from call from land owner about explosion/flowline issue.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Gas Release. Rule 912.a. 2/23/24</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>At time of inspection weather conditions were cloudy, calm, rain/snow.</p> <p>This is a summary of inspection report.</p>	medinaj	02/22/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505514	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6439428