



00064992

February 6, 1961

Memo: To the file of Bruce Sullivan, Taylor and Sullivan, and Trinidad Development, incorporated.

Subject: Lack of Cooperation on previous operations.

Several contacts have been made with the above parties regarding information on wells as itemized below. To date there has been no reply from Mr. Sullivan and Mr. Taylor referred us to Mr. Sullivan.

It is recommended that the wells listed below be pulled from the active list and no further attempt made to receive additional information unless Mr. Sullivan again operates in the State.

well file

<u>Well</u>	<u>Location</u>	<u>Remark</u>
✓ #1 T.H. Redress	SE SE 9-2N-54W	Producer that was P & A w/no record of plugging.
#4 Carlos Sandoval	NE SW 26-34S-61W	Never completed? No final reports.
#1 Roberts	SW NE 18-34S-61W	Plugging record September 1957. No completion report.
#2 Sandoval	SW SE 4-34S-62W	Intention approved June 1954. No further reports.
#3 Carlos Sandoval	SW SE 4-34S-62W	Intention approved March 1956. No further reports.
#1 Catherine Mock	SW SW 29-34S-59W	Intention approved September 1953. Water Shut off Report received September 1953. Nothing since.

Note: Mr. Taylor has been answering correspondence but states that Bruce Sullivan has the files.

✓