

well file



February 7, 1961

Mr. Jay Taylor
First National Bank Bldg.
Amarillo, Texas

Dear Mr. Taylor:

We have been attempting to contact you for some time, regarding the No. 1 Rediess well in Section 9, T-2N, R-54W.

It is our understanding that the well has been plugged, but we have not been advised of the method of plugging.

Will you please fill in a Form 6, copies enclosed, giving details, and submit at your earliest opportunity?

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

William R. Smith, Senior Petroleum Engineer

WRS:cm
Enc.

