

well file

BEST IMAGE
AVAILABLE



April 22, 1960

The Hinkler Company
Attn: W. E. Arbuckle
300 Fillmore Street
Denver, Colorado

Gentlemen:

We have completed a review of wells in the Xenia West area in T 28 N54W with particular reference to Sections 1, 2, 11 and 12. Having reviewed these well files we find that the following forms are needed on some of your wells as follows:

#1 Hinkler C NW NE Sec. 11 - A form 10, Certificate Of Clearance is required following a recompletion in the D sand.

#2 Hinkler NE NE Sec. 11 - A form 4, Notice Report of Recompletion is required showing the actual perforations. A form 10 is also required on this well.

#6 Hinkler NW SE Sec. 11 - Was apparently plugged and abandoned. Our files reflect no Notice of Intention to abandon, Form 4, which should have been submitted.

For information regarding forms requested, please refer to rule 305 on Page 11 and rule 311 on Page 12 of our Rules and Regulations.

Your compliance with the above request along with the production requested by Mr. Jersin should put our records in good shape with regard to this area. Your prompt attention to this matter will be greatly appreciated.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

William H. Smith, Senior Petroleum Engineer

WRS: ch