

Inspected Facilities

Facility ID: 484407 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [ECMC Environmental Inspection oof Trebor B12-05,19 tank battery Remediation Project 28078](#). Operator has installed one piezometer and advanced several soil borings at the location. Operator had proposed to completed remediation by 2/26/2024 (Form 27 Doc#403592415 submitted 11/10/2023). It does not appear remediation has commenced at this time. No further updates have been submitted.

Pursuant to Rule 913.d. Operator shall request any changes to the approved implementation schedule at least 14 days in advance. - OVERDUE

Operator's proposed Reporting Schedule on Form 27 Doc# 403592415: One time within 90 days of laboratory analytical receipt of site investigation samples is not approved.

Corrective Action: Operator shall submit a Supplemental Form 27 with a status update. Date: 03/08/2024

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403697451	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6441237
693701117	TreborB12-05,9 overview looking west 2-23-24	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6441228
693701118	TreborB12-05,9 piezometer 2-23-24	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6441229
693701119	TreborB12-05,9 overview looking north 2-23-24	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6441230
693701120	TreborB12-05,9 overview looking north 2-23-24 (2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6441231