

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2024

Submitted Date:

02/23/2024

Document Number:

696306023**FIELD INSPECTION FORM**Loc ID 331181 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason	303-330-1921	jason@strachanexploration.com	
Reed, Shawn		Shawn@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259124	WELL	PR	04/01/2023	OW	123-20272	FEDERAL OSPREY 35-3	PR

General Comment:

This is a Well Inspection ONLY

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Wellhead, See Photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	03/01/2024
Type	STORAGE OF SUPL		
Comment:	Used Rods, Tubing, Wellhead parts, Fencing and Secondary Containment at Wellsite. See photos **Livestock in Pasture**		
Corrective Action:	Comply with Rule 606	Date:	04/26/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	PUMP JACK		
Comment:	Fencing is in disrepair - Livestock in Pasture.		
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.	Date:	03/22/2024

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 259124

Type: WELL

API Number: 123-20272

Status: PR

Insp. Status: PR

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: TA - Well found in TA Status.
Form 42 403671289 dated 1.30.2024 for MIRU - Well suffered a frac hit. We went fishing in December - unsuccessfully - MIRU to Snub out tbg and fishing tools. Set CICR at +/-5750', check to see if that isolates pressure. If so we'll wrap up ops and plan PTA process. If no we'll run inspection log to assess what needs to be done in the PTA Planning process.

Rig is off of Well waiting for further action to be done for Plugging Operations.

Corrective Action:

Date:

COGCC Comments		
Comment	User	Date
<p>On Thursday 02/22/2024 at approximately 12:04 PM, I, Compliance Specialist Erica Petrie, conducted a Field Inspection at Strachan Exploration INC, Federal Osprey 35-3, at Location #428526 in Weld County, Colorado.</p> <p>During this Inspection the following possible Compliance Issues were observed:</p> <p>Used Rods, Tubing, Wellhead parts, Fencing and Secondary Containment at Wellsite. See photos</p> <p>**Livestock in Pasture**. Comply with Rule 606. Corrective Action Date 04.26.2024</p> <p>Unmarked Riser at Wellhead. See photos. Comply with Rule 1105. Corrective Action Date 03.01.2024</p> <p>Fencing is in disrepair - Livestock in Pasture. Install or Repair Per Rule 902.b. Corrective Action Date 03.22.2024</p> <p>A follow up on this Site Inspection will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC rules.</p>	petrie	02/23/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403698181	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6442730
696306024	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6442718