

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2024

Submitted Date:

03/05/2024

Document Number:

707901389

FIELD INSPECTION FORM

Loc ID 474767 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	All inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	
BEECHERL, ARTHUR	214-728-1840	Regulatory@verdadoil.com	all inspections
Cugnetti, Mike		Mcugnetti@verdadoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481259	WELL	DG	01/25/2024	LO	123-51639	COUNTYLINE 0508-16H	DG

General Comment:

Inspection due to complaint doc#403686804

Inspected Facilities

Facility ID: 481259 Type: WELL API Number: 123-51639 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date 2-15-2024
 Complaint Contacted: Yes via phone
 Date: 2-28-2024 Time: 1:20PM
 Location ID # 474767
 Location name: County Line pad
 Inspection Document # 698705901,921
 Complaint inspection document # 698705921
 Complaint Document form 18 # 403686804
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 2-15-2024, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Shane Hall 120 County Road 39 Brighton CO stated the issues were occurring outside of complainants home.
 On 2-28-2024, I attempted to make contact with the complainant who indicated that on 2-14-2024 complainant experienced a constant vibration at all hours of the day and night at his home.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe anything unusual in or around location. The complainant's home is approx.... 1800ft from the Location. I did set up sound study at complainants home. After reviewing data, it appears location is out of compliance with ECMC rules. Operator will need to obtain a low frequency impact study and some type of sound mitigation on site.
 At time of inspection, I spoke with Drilling supervisor he stated at time of complaint they were drilling and no unusual activity was taking place.
 Sound study attached to complaint inspection.
 Weather conditions: Clear
 Violation of ECMC Rules were observed at the time of the inspection.
 All information has been reviewed and site inspection information has been submitted to the ECMC for further review.

Corrective Action: **For low frequency issues, obtain a low frequency impact analysis and identify control measures. Per rule 423**

Date: 03/08/2024

COGCC Comments

Comment	User	Date
Will perform another sound study on 3-8-2024.	silverr	03/05/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901390	Sound stusy	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6454381