

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2024

Submitted Date:

03/13/2024

Document Number:

702403188

**FIELD INSPECTION FORM**Loc ID 319005 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242679	WELL	SI	05/01/2021	GW	123-10470	ARTHUR STROMQUIST 1	SI

**General Comment:**[This is a wellsite inspection.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate, fading and will need to be replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	electric panel, meter box, transformers & telemetry		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	242679	Type:	WELL	API Number:	123-10470	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		<div>SI, Most Recent PR records are from 4-2021. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42</div>								
Corrective Action:		<div>Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.</div>						Date:		04/13/2024
BradenHead										
Date of Last Brhd Test:		06/01/2023		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:				
		End Surf Csg Pressure:		0						
Comment:		<div>plumbed to surface.</div>								
Corrective Action:								Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On Wednesday 3-13-2024 at approximately 1445 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Location ID # 319005 Well Name: Arthur Stromquist 1 API # 05-123-10470 County: Weld Weather: Overcast, light rain. Location: Muddy with standing water on location. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues: 417.b MIT SI wells: CA Date 4-13-2024. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.	revasr	03/13/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403189	location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465736</a>