

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2024

Submitted Date:

03/21/2024

Document Number:

702502513

FIELD INSPECTION FORM

Loc ID 314930 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10775
Name of Operator: KT RESOURCES LLC
Address: 3381 WESTBROOK LANE
City: HIGHLANDS State: CO Zip: 80129

Findings:

- 14 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229906	WELL	SI	02/01/2020	GW	103-07564	FEDERAL A 5	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday, 03/19/2024, Inspector Kirby Burchett, conducted a routine field inspection at KT Resources LLC on the Federal A 5 well, Location #314930, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District, Black Bear and High Priority area with NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Random debris.
2. Oil and stained soil.
3. Cellar cover insufficient.
4. Stormwater BMP's need implementation.
5. Mechanical Integrity Test required.
6. Gas meter calibration out of compliance.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text" value="(800) 288-0560 or 911"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.		Date: <u>03/27/2024</u>

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Separator	<= 1 bbl	
Comment:	Equipment leak with stained soil		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: <u>04/04/2024</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	2 rail pipe		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.	Date:	04/19/2024
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Cellar covering inadequate		
Corrective Action:	An Operator will secure conductors and cellars to prevent accidental access by people, livestock, or wildlife when active work is not occurring.	Date:	03/30/2024
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 229906 Type: WELL API Number: 103-07564 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Production - September 2020
January 2024 Production Report
Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 04/19/2024

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater BMPs need implementation and maintenance.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 04/19/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502514	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477153