

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2024

Submitted Date:

03/15/2024

Document Number:

697602282**FIELD INSPECTION FORM**Loc ID 336288 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeterson@kpk.com	KPK environmental
, KPK		cogcc@kpk.com	All Inspections
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Anderson, Laurel		laurel.anderson@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239874	WELL	PR	09/01/2022	OW	123-07662	CHRISTENSEN UNIT 1	EI

General Comment:

This is an environmental inspection in response to Complaint Document #403715997 for the Christensen Unit 1 / Location ID / 336288. flowline. No Operator or contract personnel were onsite. Photos were attached to document the site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Signage is for the wrong location. The signage states that this location is the Christianson Unit 2; however the correct location is the Christensen Unit 1.

Corrective Action: Install sign to comply with Rule 605.

Date: 05/14/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			
Comment:	Excavation/pothole is open near the wellhead. Staining is observed within the pothole. Pothole is not adequately fenced.				
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.				Date: 03/18/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:					
Type					
Comment:	No fencing to surround the pothole. Orange cones are not adequate to prevent access.				
Corrective Action:	Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.				Date: 03/22/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	239874	Type:	WELL	API Number:	123-07662	Status:	PR	Insp. Status:	EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403721408	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6468925
697602283	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6468921
697602284	Complaint Form 18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6468922
697602285	Complaint Intake Form	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6468923
697602286	Complaint Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6468924