

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2024

Submitted Date:

03/14/2024

Document Number:

709400879

FIELD INSPECTION FORM

Loc ID 311698 Inspector Name: WOLD, REED On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 72085
Name of Operator: PETRO-CANADA RESOURCES (USA) INC
Address: 5455 BRIGHTON BLVD
City: COMMERCE CITY State: CO Zip: 80022

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| | | rbucogccinspectionreports@chevron.onmicrosoft.com | All Inspections |
| | | abbeynewby@chevron.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|---------------------------|-------------|
| 200042 | WELL | PA | 05/24/2000 | OW | 001-05044 | NOONEN UPRR 2-B | RI |
| 311698 | LOCATION | AC | | | - | NOONEN UPRR-63S59W 13NESW | RI |

General Comment:

This is a final and stormwater inspection for well pad and access road. Corrective actions observed during inspection include weeds (russian thistle, bull thistle & Kochia) stormwater erosion on access road and base soil in reclaimed area. Petro-Canada is a subsidiary of Noble energy, hence forth a subsidiary of Chevron through its acquisition of Noble energy.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.

Corrective Action:

Comply with Rule 606. weeds

Date:

03/22/2024

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 200042 Type: WELL API Number: 001-05044 Status: PA Insp. Status: RI

Facility ID: 311698 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment **Bare soil in Reclaimed areas**

Corrective Action **Comply with rule 1002, soil protection** Date **03/22/2024**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Final reclamation areas are not progressing towards 1004 revegetation standards. Perform reclamation per Rule 1004. Reseeding of native vegetation appears to be needed to meet total perennial, non-invasive uniform plant cover of at least 80 percent of reference area levels. Use surface owner seed mixture, coordinate with surface owner to acquire required mixture. Ensure erosion controls are implemented to stabilize the reseeded soil, and continue to monitor and manage the site. Weeds should be controlled in order to not impede the perennial vegetation establishment. See good housekeeping.

Corrective Action: **Comply with rule 1004. reclamation** Date **04/01/2024**

Overall Final Reclamation **Fail** Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: **Stormwater erosion on access road to site. Coordinates with other operators in the area to address the access road issues.**

Corrective Action: **Comply with rule 1002. stormwater** Date: **03/22/2024**

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403721858 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6469371 |
| 709400892 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6469339 |