

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403711699

Date Received:

03/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

(970) 285-9377

COGCCInspectionReports@terraep.com

Kellerby, Shaun

(970) 712-1248

shaun.kellerby@state.co.us

Thompson, Bud

(970) 878-3828

BLThomps@BLM.gov

COGCC INSPECTION SUMMARY:

FIR Document Number: 702501937

Inspection Date: 10/09/2023

FIR Submit Date: 10/09/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 419254

Location Name: Federal RGU

Number: 23-23-198

County: _____

Qtrqtr: NESW

Sec: 23

Twp: 1S

Range: 98W

Meridian: 6

Latitude: 39.946904

Longitude: -108.362654

FACILITY - API Number: 05-103-

-00

Facility ID: 419254

Facility Name: Federal RGU

Number: 23-23-198

Qtrqtr: NESW

Sec: 23

Twp: 1S

Range: 98W

Meridian: 6

Latitude: 39.946904

Longitude: -108.362654

CORRECTIVE ACTIONS:

1 CA# 183546

Corrective Action: All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.

Date: 10/17/2023

Response: CA COMPLETED

Date of Completion: 11/21/2023

Debris has been removed from location. Corrective Action complete.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 183547

Corrective Action: Close and seal gauge hatches when not accessing tank per Rule 608.a.(9).

Date: 10/10/2023

Response: CA COMPLETED

Date of Completion: 10/10/2023

Operator
Comment:

Hatch has been closed. Corrective Action complete.

COGCC Decision:

COGCC
Representative:

3 CA# 183548

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 10/24/2023

Response: CA COMPLETED

Date of Completion: 10/23/2023

Operator
Comment:

Guy line anchor has been properly marked. Corrective Action complete.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA#183546: Debris has been removed from location. Corrective Action complete.
CA#183547: Hatch has been closed. Corrective Action complete.
CA#183548: Guy line anchor has been properly marked. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 3/26/2024 6:16:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files