



99999999

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

ORADO Federal lands.

MAY - 5 1970

COLO. OIL & GAS CONS. COMM.

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR  
Consolidated Oil & Gas, Inc.

3. ADDRESS OF OPERATOR  
1860 Lincoln St. Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface  
At proposed prod. zone  
NW SW NW Sec. 16, T9N, R56W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
4,518' KB (4,509') GL

5. LEASE DESIGNATION AND SERIAL NO.  
State "A" (55-406)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
State "A"

9. WELL NO.  
#2

10. FIELD AND POOL, OR WILDCAT  
Cotton Valley

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA  
Sec. 16, T9N, R56W

12. COUNTY OR PARISH  
Weld

13. STATE  
Colo.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input checked="" type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

April 1, 1970 Pulled rods & tubing. Ran 100 gal. sand to 5743', dumped 20 sax cement to 5661'. Shot casing, came loose @ 4513', pulled. Mud hole to 168', dumped 10 sax cement and mud to 15', dumped 5 sax cement to top.

Plugged by Donnelly Casing Pulling Co.

65-123-65673

DVR	
FJP	✓
HHM	✓
JAM	✓
JJD	✓

Gas Ex ~~Prod.~~ Prod.

18. I hereby certify that the foregoing is true and correct

SIGNED Wayne Rogan TITLE Prod. Mgr., JIP DATE 5-4-70

(This space for Federal or State office use)

APPROVED BY W. Rogan TITLE DIRECTOR O & G CONS. COMM. DATE MAY 7 1970

CONDITIONS OF APPROVAL, IF ANY:

