

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2024

Submitted Date:

04/08/2024

Document Number:

697505246

FIELD INSPECTION FORMLoc ID 415742 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 27742

Name of Operator: EOG RESOURCES INC

Address: P O BOX 4362

City: HOUSTON State: TX Zip: 77210-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		kristen_limongelli@eogresources.com	
		tracy_opp@eogresources.com	
		penny.garrison@state.co.us	
		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416058	WELL	AL	05/26/2016	LO	123-31245	Garden Creek 3-05H	RI

General Comment:

This is a Final Reclamation inspection in response to ECMC Field Inspection Report (FIR) Doc.# 696306059 submitted on March 5, 2024.

Inspected Facilities										
Facility ID:	416058	Type:	WELL	API Number:	123-31245	Status:	AL	Insp. Status:	RI	
Idle Well										
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		<div>Comment from previous FIR: AL - Conductor and Well Celler appear to still be present at Wellsite. Form 4 Sundry #2452104 for Abandon Permit was filed on 05.27.2016 and Approved on 08.15.2016. Indicating that operation has not been conducted. Well has not been drilled. Location has not been constructed and site will not be used in the future. Inspection demonstrates that location construction and some part of wellbore was initiated without appropriate documentation.</div>								
Corrective Action:		<div>Corrective Action from previous FIR: Operator is to provide full description of activity and current status at this location. Location and APD were indicated to have been abandoned without construction or drilling (Sundry #2452104). Provide these details on a Form 4 Sundry Notice. If any casing was placed, a Form 5 Drilling Completion Report is required. Final reclamation and pad closure need to be concluded. Operator has failed to perform the corrective action; therefore, the corrective action remains applicable.</div>						Date:		04/02/2024

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built **Fail** _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

<p>Operator submitted a Form 4 (Doc.# 2452104) on 5/27/2016 to abandon the permit and that the location has not been constructed.</p> <p>Based on Google Earth from 9/7/2013 and 2024 field inspections, the location was constructed and conductor set. Refer to the attached inspection photos.</p> <p>On 4/8/2024, ECMC Reclamation Specialist left a voicemail with the Principal Agent regarding the observed compliance issue.</p>		Date 04/30/2024
Corrective Action:	<p>Comply with Rule 1004. Remove all surface equipment, remove gravel and recontour. All areas compacted by drilling and subsequent oil and gas operations shall be cross-ripped to a depth of eighteen (18) inches. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.</p>	
<p>Overall Final Reclamation Fail Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/></p>		

COGCC Comments		
Comment	User	Date
To date, the Operator has not reached out to ECMC Staff and the corrective action from the previous inspection has not been resolved.	binschusc	04/08/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
697505247	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6499987