

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403729992

Date Received:
03/25/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708200983
Inspection Date: 03/11/2024 FIR Submit Date: 03/13/2024 FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 433511

Location Name: State North Platte Number: F-36 Pad County: _____
Qtrqtr: NWN Sec: 36 Twp: 5N Range: 63W Meridian: 6
W
Latitude: 40.362369 Longitude: -104.392372

FACILITY - API Number: 05-123- -00 Facility ID: 433511

Facility Name: State North Platte Number: F-36 Pad
Qtrqtr: NWN Sec: 36 Twp: 5N Range: 63W Meridian: 6
W
Latitude: 40.362369 Longitude: -104.392372

CORRECTIVE ACTIONS:

1 CA# 192990

Corrective Action: Fence or cover open excavations to prevent access when sites are not attended per Rule 913.b.(5)B.i. Date: 03/14/2024

Response: CA COMPLETED Date of Completion: 03/14/2024

Operator Comment: Operator has reported that all open excavations/holes have been backfilled as of 3/14/2024.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 CA# 192991

Corrective Action: Comply with Rule 1002.c.

Date: 03/20/2024

Response: CA COMPLETED

Date of Completion: 03/22/2024

Operator Comment: Operator reported that the location has been hydromulched to address/prevent erosion and provide stabilization. The location has also been re-seeded and straw crimped to establish desirable vegetation to comply with reclamation rules.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 3/25/2024 1:04:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403729992	FIR RESOLUTION SUBMITTED
403730013	Inspection Resolution Report

Total Attach: 2 Files