

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2024

Submitted Date:

04/10/2024

Document Number:

702502587

FIELD INSPECTION FORMLoc ID 315333 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 34720

Name of Operator: GORDON ENGINEERING INC

Address: PO BOX 113

City: SPRINGDALE State: UT Zip: 84767

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bryan, Nicholas	(385) 250-4548	nickbryan85@gmail.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230645	WELL	PR	12/01/2021	GW	103-08313	FEDERAL 24-1	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 04/09/2024, Inspector Kirby Burchett, conducted a routine field inspection at Gordon Engineering Inc. on the Federal 24-1 well, Location #315333, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District, Black Bear and High Priority Habitat area with Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Unused equipment on location.
2. Relief risers missing rain protectors.
3. Gas meter calibration out of date.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-618-0811 or 911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Evidence of last year's weeds. Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Old meter run? Door silted shut. Burner on separator inoperable. Separator in use or bypassed?		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.		Date: 04/25/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	PIT		
Comment:	Livestock wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.		Date: 05/10/2024
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		

Comment:	Wellhead tree. Plumbing to flowline is misaligned and in stress. Future failure is a possibility. Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.			
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:	Heater tubes inoperable. Silted in. Relief risers missing rain protection.			
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.		Date:	04/25/2024

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	230645	Type:	WELL	API Number:	103-08313	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	January 2024 Production Report								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 103866Lat: 39.855920Long: -108.673427

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:Fencing Type: Livestock

Fencing Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: None

Corrective Action: _____

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Comment: _____

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403749655	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503154
702502588	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503151