

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2024

Submitted Date:

04/20/2024

Document Number:

715200085

FIELD INSPECTION FORMLoc ID 321852 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 59925

Name of Operator: MONUMENT GAS MARKETING INC

Address: P O BOX 950

City: MONUMENT State: CO Zip: 80132-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Taylor, Chad		chad.taylor@state.co.us	
Campbell, Randy		rcampbell0614@comcast.net	
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208225	WELL	SI	08/01/2021	DSPW	017-07160	COE TRUST 12B-18 2	SI

General Comment:

Routine UIC Inspection

Location**Lease Road:**

Type	Access		
comment:	Trail through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign laying on the ground needs installed and updated to current operator		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/17/2024

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	There is a skim of crude oil on the ground at the wellhead. Remove stained soil			
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.			Date: 04/27/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	208225	Type:	WELL	API Number:	017-07160	Status:	SI	Insp. Status:	SI
Underground Injection Control									
UIC Violation:		Maximum Injection Pressure:							
UIC Routine									
Inj./Tube:	Pressure or inches of Hg	0 PSIG	Previous Test Pressure		MPP				
	(e.g. 30 psig or -30" Hg)				Inj Zone:		STLSP		
TC:	Pressure or inches of Hg	0 PSIG	Previous Test Pressure		Last MIT:		05/28/2019		
Brhd:	Pressure or inches of Hg		Previous Test Pressure		AnnMTReq:		NO		
Comment:	CASING HAD A LIGHT BLOW, DIED IMMEDIATELY. TBG VALVE IS OPEN AND TBG WAS DEAD AT TIME OF INSPECTION								
Corrective Action:							Date:		
Method of Injection: GRAVITY FEED									
Test Type:			Tbg psi:			Csg psi:			BH psi:
Insp. Status:									
Comment:									
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access have been farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Form 6A (403368542) has been approved with a plug date of 12/31/27. Operator needs to file a Form 6 (Notice of Intent to Abandon) with Engineering. Pumper needs to close wellhead tubing valve immediately. NO INJECTION IS ALLOWED once well is placed "Out of Service"	welshb	04/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200097	Wellhead photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6517606