

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403762854

Date Received:

04/22/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900513

Inspection Date: 04/04/2024

FIR Submit Date: 04/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 429893

Location Name: Latham 14-12 Number: Facility County: _____

Qtrqtr: SESE Sec: 11 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.320820 Longitude: -104.397570

FACILITY - API Number: 05-123-00 Facility ID: 429893

Facility Name: Latham 14-12 Number: Facility

Qtrqtr: SESE Sec: 11 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.320820 Longitude: -104.397570

CORRECTIVE ACTIONS:

1 CA# 194144

Corrective Action: Comply with Rule 606 to remove weed debris.

Date: 04/16/2024

Response: CA COMPLETED

Date of Completion: 04/19/2024

Operator Comment: Operator has reported that the location has been mowed to address undesirable vegetation and tumbleweeds have been cleared to comply with Rule 606. Operator has also noted that the location/flowline corridor has been inter-seeded, and straw crimped to promote vegetation.

ECMC Decision: _____

ECMC
Representative:

2 CA# 194145

Corrective Action: Remove fencing to comply with Rule 1004.

Date: 05/09/2024

Response: CA COMPLETED

Date of Completion: 04/19/2024

Operator Comment: Operator has reported that the barbed wire fencing has been removed around the flowline corridor and facility pad to comply with Rule 1004.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 4/22/2024 7:58:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403762864	Inspection Resolution Report
-----------	------------------------------

Total Attach: 1 Files