

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2024

Submitted Date:

04/16/2024

Document Number:

702502605

**FIELD INSPECTION FORM**

Loc ID 314515 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 760 HORIZON DRIVE STE 401  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Wilson Creek		rbucogccinspectionreports@chevron.onmicrosoft.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Olson, Andrew	(970) 257-6079	andrewolson@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228892	WELL	SI	10/01/2021	GW	103-05888	WILSON CREEK UNIT 18	PA

**General Comment:**

[ECMC Inspection Report Summary](#)

On Tuesday, 04/16/2024, Inspector Kirby Burchett, conducted a routine field inspection at Chevron USA Inc on the Wilson Creek Unit 18 well, Location #314515, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and High Priority Habitat area with NSO, Density and Other Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

- Well has been plugged and abandoned. Awaiting reclamation. Database indicates PA status as of June 2023. No Form 6 – Subsequent Report of Abandonment on file.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(877) 257-6007 or 911		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Other	# 1		
Comment:	Well has been plugged, cut off and capped.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 228892 Type: WELL API Number: 103-05888 Status: SI Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in since October 2021.  
PA status since June 2023.  
No Form 6 - Subsequent Report of Abandonment in database.

Corrective Action: Submit Form 6 - Subsequent Report of Abandonment to ECMC. Date: 05/17/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403757111	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511164">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511164</a>