



00241767

Interoffice OGCC-1
Rev. 7/8/55VERBAL REQUESTS

NOTICE OF INTENTION TO DRILL _____

Bonding Status _____

NOTICE OF INTENTION TO ABANDON X

OTHER _____

| | | | |
|--|----|--|--|
| | | | |
| | | | |
| | 27 | | |
| | 6 | | |

COMPANY MasiniBY Bill Allison

ADDRESS _____

Title _____

LEASE CraigWELL NUMBER 1BCOUNTY WeldFIELD Weld W/CLOCATION - By Quarters SESW Sec. 27 Twp. 9N R 56W Mer. 6thThe Well is located _____ ft. (N) of Section Line, and _____ ft. (E) of Section line.
(S) (W)DETAILS OF PLAN OF WORK: T.D. 5880 FORMATION _____ESTIMATED DATE OF WORK: June 30, 1959 ESTIMATED TIME: 4 PMno cores DST 5642-51(D) TOLK Get 53 min SIP 1472
rev. 950' OCW 15' oil5751-57(J) T02 450' H₂Odue to limited permeability & reasonably uniform pressureno migration should occur from D to Jmust not plug top of bottom of surfaceAPPROVED BY: WRSDATE June 30, 1959

Visited 7-6-59

Rig & equipment still on location
Not ~~evidence~~ ^{certain} of plug bottom of surface??
& none on top surface casing. ✓

DUR