

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2024

Submitted Date:

04/25/2024

Document Number:

697602344

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Ahmadian, Alexander On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485890	SPILL OR RELEASE	CL	01/18/2024		-	Deborah 7-5 Flowline	EI

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 485890. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Broken glass was seen on location. The door from the meter shed has broken off.

Corrective Action: Comply with housekeeping Rule 606.

Date: 05/02/2024

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type

OTHER

Comment: Orange fencing around the excavation is beginning to fall.

Corrective Action: The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.

Date: 05/02/2024

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 485890 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Inadequate		
Comment	There are several unmarked stockpiles on location.			
Corrective Action	Operator shall properly dispose of oily waste in accordance with Rule 905.e. Additionally, Operator shall manage waste in compliance with Rule 913.b. (5)B and ECMC Guidance 913.b.(5)B i-v.			Date: 05/02/2024

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403770039	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6524771">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6524771</a>
697602345	Photolog	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6524770">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6524770</a>