

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2024

Submitted Date:

05/02/2024

Document Number:

699700360**FIELD INSPECTION FORM**Loc ID 322396 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS ST STE 6161City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arnim, Rees	(713) 469-0275	rarnim@locin.energy	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111792	PIT				-	LEWIS USA 36-1	EI
111793	PIT	CL			-	LEWIS USA 36-1	EI
210408	WELL	SI	10/01/2023	GW	045-06164	LEWIS USA 36-1	SI

General Comment:4/29/2024 ECMC Environmental Inspection.

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Mislabeled 300 bbl crude oil tank.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 06/02/2024
Type	TANK LABELS/PLACARDS			
Comment:	Mislabeled 40 bbl produced water PBV.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 06/02/2024
Type	TANK LABELS/PLACARDS			
Comment:	Mislabeled 60 bbl produced water PBV.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 06/02/2024
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: <input type="text"/>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: <input type="text"/>

Inspected Facilities

Facility ID:	111792	Type:	PIT	API Number:	-	Status:		Insp. Status:	EI
--------------	--------	-------	-----	-------------	---	---------	--	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	111793	Type:	PIT	API Number:	-	Status:	CL	Insp. Status:	EI
--------------	--------	-------	-----	-------------	---	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	210408	Type:	WELL	API Number:	045-06164	Status:	SI	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
For Pit Facility ID 111792, Operator shall comply with Rule 909.a and ensure that the Pit is properly permitted through a Form 15 approved by the Director, accurately mapped and listed according to current facility records in the Commission's database. Operators may update facility records using a Form 15. CA dates: 6/2/2024	heilj	05/02/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700361	20240429 Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6533404