

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign is not visilbe on wellhead sign, due to automation equipment that is attached to wellhead sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/17/2024

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 244950 Type: WELL API Number: 123-12745 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 4/17/24 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Rocky Mountain Fuel C-10 Company Name- KPK API- 05-123-12745 In Weld County Colorado. While there, I observed PR well. During this inspection the following possible compliance issues were observed: Wellhead sign. Rule 605 d. 5/17/24 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	04/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403771170	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6526139
699505705	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6526097