

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403533617

Date Received:

09/18/2023

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

Krystal Heibel

303-817-5217

krystal.heibel@state.co.us

Dolezal, Pat

(970) 332-3585

pat.dolezal@ownresources.com

Quint, Craig

craig.quint@state.co.us

### ECMC INSPECTION SUMMARY:

FIR Document Number: 709100107

Inspection Date: 08/31/2023

FIR Submit Date: 09/08/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

### LOCATION - Location ID: 337000

Location Name: SALVADOR-64N46W

Number: 5NENE

County: YUMA

Qtrqtr: NENE

Sec: 5

Twp: 4N

Range: 46W

Meridian: 6

Latitude: 40.349835

Longitude: -102.530003

### FACILITY - API Number: 05-125-

-00

Facility ID: 281392

Facility Name: SALVADOR

Number: 7-5

Qtrqtr: NENE

Sec: 5

Twp: 4N

Range: 46W

Meridian: 6

Latitude: 40.349835

Longitude: -102.530003

### CORRECTIVE ACTIONS:

1 CA# 180556

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Operator shall identify the unmarked valve near the wellhead.

Date: 09/23/2023

Response: CA COMPLETED

Date of Completion: 09/13/2023

Water line has been plugged

Operator Comment: \_\_\_\_\_

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

2 CA# 180557

Corrective Action: Operator shall update the pit location (including accurate latitude and longitude) within an updated Form 15.

Date: 10/09/2023

Response: CA COMPLETED

Date of Completion: 09/18/2023

Operator Comment: Operator is in process to research historical Google Earth to try and determine actual historic location of pit. Operator at time of inspection had submitted Form 27 Doc#403509794 on 8/25/23 to start process to close pit. Included in Form 27 Doc# 403509794 were statements that operator was unable to locate registered pit. There is no current indication of pit at registered location or within vicinity of wellhead or meter shed. Operator asks for guidance if unable to locate pit location as operator does not want to submit knowingly incorrect data on Form 15

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 9/18/2023 3:21:49 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403533617	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files