

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
402846171

Date Received:
10/19/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 6720
Name of Operator: ROBERT L BAYLESS PRODUCER LLC
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Trujillo, Helen</u>		<u>htrujillo@rbayless.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 694500356
Inspection Date: 06/17/2021 FIR Submit Date: 07/07/2021 FIR Status: _____

Inspected Operator Information:

Company Name: ROBERT L BAYLESS PRODUCER LLC Company Number: 6720
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

LOCATION - Location ID: 316758

Location Name: DRY CREEK UNIT-65N88W Number: 22NENW County: _____
Qtrqtr: NENW Sec: 22 Twp: 5N Range: 88W Meridian: 6
Latitude: 40.379961 Longitude: -107.248449

FACILITY - API Number: 05-107-00 Facility ID: 316758

Facility Name: DRY CREEK UNIT-65N88W Number: 22NENW
Qtrqtr: NENW Sec: 22 Twp: 5N Range: 88W Meridian: 6
Latitude: 40.379961 Longitude: -107.248449

CORRECTIVE ACTIONS:

1 CA# 152468

Corrective Action: Remove contaminated soil from wellhead and prevent future releases. Date: 08/07/2021

Response: CA COMPLETED Date of Completion: 08/26/2021

Operator Comment: Removing while removing pit soils to landfill. ETA compelled by 10/22/2021.

ECMC Decision: _____

ECMC
Representative:

2 CA# 152469

Corrective Action: close project per COGCC rules. Per Rule 915.f, if the remediation project is not completed by January 15, 2022, soil shall comply with Table 915-1.

Date: 01/15/2022

Response: CA COMPLETED

Date of Completion: 10/19/2021

Operator
Comment: Soil analytical results submitted on Form 27-S doc ID 402846265.

ECMC Decision:

ECMC
Representative:

3 CA# 152470

Corrective Action: no need to repair as pit is not a threat and being closed.

Date: 07/07/2021

Response: CA COMPLETED

Date of Completion: 10/19/2021

Operator
Comment: Pit being closed as part of REM 15107.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: HELEN TRUJILLO

Signed:

Title: PROD & REG ANALYST

Date: 10/19/2021 11:40:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402846171	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files