

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403777813

Date Received:

05/02/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 88265

Name of Operator: TIGGES OIL LLC

Address: 12406 WCR 64 1/2

City: GREELEY State: CO Zip: 80631

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Julie Branting</u>	<u>303 638-7484</u>	<u>petropro@comcast.net</u>
<u>Tigges, Kenneth</u>	<u>970-396-8381</u>	<u>levi.tigges@gmail.com</u>
		<u>jesse.tigges@gmail.com</u>
		<u>jesse.tigges@gmail.com</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Tigges, Kenneth</u>	<u>970-396-8381</u>	<u>levi.tigges@gmail.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 679605037

Inspection Date: 08/26/2022

FIR Submit Date: 08/29/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TIGGES OIL LLC

Company Number: 88265

Address: 12406 WCR 64 1/2

City: GREELEY State: CO Zip: 80631

LOCATION - Location ID: 327053

Location Name: TIGGES-66N66W Number: 31NENW County: _____

Qtrqtr: NENW Sec: 31 Twp: 6N Range: 66W Meridian: 6

Latitude: 40.449253 Longitude: -104.823574

FACILITY - API Number: 05-123-00 Facility ID: 327053

Facility Name: TIGGES-66N66W Number: 31NENW

Qtrqtr: NENW Sec: 31 Twp: 6N Range: 66W Meridian: 6

Latitude: 40.449253 Longitude: -104.823574

CORRECTIVE ACTIONS:

1 CA# 164163

Corrective Action:

Date: 06/09/2021

Conduct maintenance on equipment, cleanup stained material and review self inspection processes. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.

Response: CA COMPLETED

Date of Completion: 04/24/2024

Operator Comment: Stained soil removed, contained, waiting on manifest and transport to proper facility. see attached picture

ECMC Decision:

ECMC Representative:

2 CA# 164164

Corrective Action: Install sign to comply with Rule 605.d.

Date: 06/09/2021

Response: CA COMPLETED

Date of Completion: 04/18/2024

Operator Comment: Sign corrected, see attached picture

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Julie Branting

Signed:

Title: Agent

Date: 5/2/2024 5:58:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403777813	FIR RESOLUTION SUBMITTED
403777821	WH Remediation pic
403777822	WH sign pic

Total Attach: 3 Files