

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401999349

Date Received:

04/08/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 674902642

Inspection Date: 03/01/2019

FIR Submit Date: 03/14/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 305083

Location Name: Stonebraker Number: 28W-HZ Pad County: \_\_\_\_\_

Qtrqtr: SENE Sec: 28 Twp: 2N Range: 64W Meridian: 6

Latitude: 40.111300 Longitude: -104.547680

### FACILITY - API Number: 05-123-00 Facility ID: 305083

Facility Name: Stonebraker Number: 28W-HZ Pad

Qtrqtr: SENE Sec: 28 Twp: 2N Range: 64W Meridian: 6

Latitude: 40.111300 Longitude: -104.547680

### CORRECTIVE ACTIONS:

1 CA# 123226

Corrective Action: Perform reclamation in accordance to COGCC 1004 reclamation rules and requirements. Operator is directed to perform corrective actions outlined on this inspection report immediately. Doing so may decrease the duration of the alleged violations and the penalties that may be assessed pursuant to Rule 523.

Date: 03/01/2019

Response: CA COMPLETED

Date of Completion: 04/08/2019

Operator  
Comment:

CA has been addressed and reclamation work has been completed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 123227

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 03/01/2019

Response: CA COMPLETED

Date of Completion: 04/08/2019

Operator  
Comment:

CA has been addressed and erosion controls have been completed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA's have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: \_\_\_\_\_

Title: EHS Coordinator

Date: 4/8/2019 11:05:00 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401999349	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files