

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403442842

Date Received:
06/22/2023

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

2 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tammy Jones</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 712700307
Inspection Date: 06/20/2023 FIR Submit Date: 06/21/2023 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306974

Location Name: ALLISON UNIT-N32N6W Number: 19NENE County: LA PLATA
Qtrqtr: NENE Sec: 19 Twp: 32N Range: 6W Meridian: N
Latitude: 37.006187 Longitude: -107.533997

FACILITY - API Number: 05-067-00 Facility ID: 288582

Facility Name: ALLISON UNIT Number: 116S
Qtrqtr: NENE Sec: 19 Twp: 32N Range: 6W Meridian: N
Latitude: 37.006187 Longitude: -107.533997

CORRECTIVE ACTIONS:

1 CA# 173440

Corrective Action: Recover free liquids and properly dispose in accordance with 905.c. Clean up and properly dispose of impacted material. Rule 1002.f. Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 06/22/2023

Response: CA COMPLETED Date of Completion: 06/22/2023

Tightened the pumping unit packing. I removed stained dirt around the wellhead and cleaned up the wellhead.

Operator
Comment:

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

2 CA# 173441

Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.

Date: 07/21/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator
Comment: BH Tests are done Annually before year-end

ECMC Decision: **Not Approved**

ECMC
Representative: Date changed in FIR.

3 CA# 173442

Corrective Action: Rule 1002.f. Site stabilization.

Date: 07/05/2023

Response: CA COMPLETED

Date of Completion: 06/22/2023

Operator
Comment: Stabilized location and filled in ruts.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Resolved photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 6/22/2023 2:49:35 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403442842	FIR RESOLUTION SUBMITTED
403442867	Resolved Photos

Total Attach: 2 Files