

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
402885889

Date Received:  
12/28/2021

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10679  
Name of Operator: LOGOS OPERATING LLC  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Rowley, Darren</u>	<u>505-947-4974</u>	<u>drowley@logosresourcesllc.com</u>
<u>Trujillo, Etta</u>		<u>etrujillo@logosresourcesllc.com</u>
<u>Florez, Marie</u>		<u>mflorez@logosresourcesllc.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 700300298  
Inspection Date: 11/09/2021 FIR Submit Date: 11/11/2021 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: LOGOS OPERATING LLC Company Number: 10679  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87401

**LOCATION** - Location ID: 325204

Location Name: BONDAD 33-10-N33N10W Number: 3SESE County: LA PLATA  
Qtrqr: SESE Sec: 3 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.128430 Longitude: -107.917970

**FACILITY** - API Number: 05-067-00 Facility ID: 214267

Facility Name: BONDAD 33-10 Number: 4  
Qtrqr: SESE Sec: 3 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.128430 Longitude: -107.917970

**CORRECTIVE ACTIONS:**

**1** CA# 157711

Corrective Action: Retroactively submit electronic from 42 notice of well liquids unloading Date: 11/12/2021

Response: CA COMPLETED Date of Completion: 12/02/2021

Operator Comment: LOGOS submitted a Form 42 due to unloading the well manually and pumper was unaware of the process. LOGOS reviewed rules 405.s and 903.d (1) and regulatory met with the pumper to ensure this would not occur again.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: LOGOS submitted a Form 42 due to unloading the well manually and pumper was unaware of the process. LOGOS reviewed rules 405.s and 903.d (1) and regulatory met with the pumper to ensure this would not occur again.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Marie E. Florez

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 12/28/2021 6:02:40 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402885889	FIR RESOLUTION SUBMITTED
402885909	Form 42

Total Attach: 2 Files